## **CORNING**

This notification concerns the temporary removal of blue colorant used in the manufacturing process of 15 and 50mL Falcon® caps for Falcon® Centrifuge Tubes. Due to global raw material shortages, Corning® is producing Falcon® caps without blue colorant resulting in a natural colored cap (see images). The natural cap has been validated through Corning's standard process and passed functional testing that was performed. There is no change to the tube itself, only the cap. Change is effective immediately.

There will be no change to the centrifuge tube materials, graduation marks, product artwork, or any other change that would impact the form, fit, and/or function of the product. Additionally, the same in-process and post-process inspections will be performed for the cap.

There will be no change to the centrifuge tube materials, graduation marks, product artwork, or any other change that would impact the form, fit, and/or function of the product. Additionally, the same in-process and post-process inspections will be performed for the cap.

As this is only a change to the cap, product claims and product functionality remain unchanged.

## **AFFECTED PRODUCTS:**

3-352096, 3-352196, 3-352095, 3-352099, 3-352097, 3-290020, 3-358206, 3-352098, 3-352070

Cap without colorant (Alternative)



Standard Falcon cap with colorant

